data·pixel
pixels at work

Quick Start Guide

PCI Express

The enclosed PCI Express (PCIe) x4 card with 4 USB 3.0 ports is required to guarantee the optimum data transmission rate between the supplied Data-Pixel metrology instrument and your computer.
These instructions show you how to install this electronics board card in your desktop computer (full sized tower or mini tower required).

If you have any questions, please contact Data-Pixel technical support:
+33 450 673 980 - info@data-pixel.com

Hardware setup:

1 Shut down

2 Unplug all cables

3

4 Identify and remove slot cover

5 ! Ground yourself!

6 Take out PCI card from package

! Don't touch electronics

7

8

9 Plug cable

12 Boot up

11 ! No USB cables on PCI card

10

13 Install new drivers

> Data-Pixel installer (F:) >

Run "RENESAS.exe"

Nom

RENESAS-USB3-Host-Driver-30230-setup.exe

14 Connect Data-Pixel machine on PCI Express