
FO-IS Fiber Optic Insulation Stripper Instruction Sheet

Warning! This tool should not be used on live electrical circuits. It is not protected against electrical shock! Always use OSHA/ANSI/CE or other industry approved eye protection when using tools. This tool is not to be used for purposes other than intended. Read carefully and understand instructions before using this tool



FO-IS Fiber Optic Insulation Stripper

- Removal of outer sheath from 3.0*2.0 flat FTTH fiber cable for connectorization.
- Suitable for both steel and Keylar strength members
- Soft gripped handle
- Length scale
- Lightweight, durable, compact
- Exercise caution when handling bare fiber
- Observe care when handling tool





Specifications

- p	
Fiber Type	1,2 Core FTTH, GJXH, GJXV
Outer Coverage	Indoor 3.0mm x 2.0mm
Fiber Coating	250 and 900 micron
Fiber Cladding	125 micron
Tool Size	30mm x 110mm x 20mm
Blade Life	Metal Core – 1000 cycles
	Nonmetallic Core – 2000 cycles

WARRANTY: RIPLEY warrants its products against defective materials and workmanship for a period of one year from date of shipment from the RIPLEY factory provided the product is utilized in accordance with instructions and specified ratings.



